



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIAN AGIP OIL COMPANY (NOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 24/5/2016 ii. Date first reported: 24/5/2016
iii. Date of first investigation: 25/5/2016 iv. Spill Incidence No: 2016/SAR/076/117
v. Date of follow-up investigation: / / /
vi. Time investigation started: 1:05 PM
vii. Estimated quantity spilled(bbls): 2.03 BBLs viii. Quantity Recovered: NIL
4. Site Details
i. Site/Location: 18" TEBIDABA/BRASS PIPELINE AT LASUKUGBENE
ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW
iv. Spill Co-ordinates: N(m): (i) NO4° 30' 31.8" (ii) NO4° 30' 31.9"
E(m): E 006° 02' 26.6" E 006° 02' 26.6"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
vi. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify) Riser
iv. Cause Of Spill.
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....

i. Properties impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify) SOME PART OF THE PLANTAIN VEGETATION

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☒ Crops ☒ Fish Farm/ Pond ☒ Fishing net ☒ Makeshift
☒ Permanent ☒ Others PLANTAIN PLANTATION

8. Extent of Impact

a) Community (indicate name)

- i.
 ii. NIL
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii. NIL
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>/</u>	<u>/</u>	<u>/</u>	<u>/</u>

8. Photograph/Map/Chart Ref.

☒ Still photographs

☒ Video coverage

☒ Mapping

9. Samples taken.....

NO

10. Investigation carried out by

☒ Foot

☒ Boat

☒ Aircraft

11. Remarks/Recommendation

NAOC SHOULD CARRY-OUT CLEAN-UP
AND ALSO INTENSIFY SECURITY SURVEILLANCE
AROUND ITS FACILITY.

1:05 PM - 2:00 PM