

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIA AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
i. Date of Incident: 04/03/2016 ii. Date first reported: 04/03/2016
iii. Date of first investigation: 04/03/2016 iv. Spill Incidence No. 2016/SAR/045
v. Date of follow-up investigation: 04/03/2016
vi. Time investigation started: 14:00 HRS
vii. Estimated quantity spilled(bbls): 0.20 BBLs viii. Quantity Recovered: 0.30 BBLs
4. Site Details
i. Site/Location: 10" CLOUGH CREEK/TEBIDABA PIPELINE @ AZUZUAMA
ii. State: BAYELSA iii. L.G.A: SOUTHERN IJAW
iv. Spill Co-ordinates: N(m) 4° 40' 17.1"
E(m) 6° 05' 54" 33.0"
v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
vi. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify).....
iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☒ Others (specify).....
iv. Cause Of Spill.
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (specify).....
v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....



i. **Properties impacted by the incident**

☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (specify).....

ii. **Nature of impact**

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....

iii. **Delineation of impacted area**

☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. **Type of properties/ structures, if any, found outside the right-of-way**

☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. **Extent of Impact**

a) **Community (indicate name)**

i.
 ii.
 iii.
 iv.

b) **Land (indicate area in m²)**

i.
 ii.
 iii.
 iv.

b) **Creeks/Creek lets** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) **Swamp**

☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) **River**

☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) **Shoreline/water**

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Rel.

☒ Still photographs ☒ Video coverage ☒ Mapping

10. Samples taken.....

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation..... Unknown person(s) installed 2" valve on the facility at 12 o'clock position for oil theft activities.

13. Time investigation ended 17:01 HRS