

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NIGERIA ACIP OIL COMPANY (NATOC)
2. Type of Complaint/Incident:
 - ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
 - ☒ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 15/10/2016 ii. Date first reported: 15/10/2016
 - iii. Date of first investigation: 15/10/2016 iv. Spill Incidence No: 2016/SAR/N4/032
 - v. Date of follow-up investigation: 15/10/2016
 - vi. Time investigation started: 1:30pm
 - vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: 18" TEBIDABA/BRASS @ OYEREGBENE
 - ii. State: BAYELSA iii. L.G.A: SOUTHERN IDAW
 - iv. Spill Co-ordinates: N(m) 04° 29' 47.7"
E(m) 006° 04' 31.7"
 - v. Spill area
 - ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
 - ☒ Near shore ☒ Offshore ☒ Others (specify).....
 - vi. Structural Controls in Place
 - ☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
 - ☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
 - ii. Type of Oil contaminant
 - ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
 - ☒ Others (specify)
 - iii. Facility
 - ☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
 - ☒ Storage Tank ☒ Compressor Plant ☒ Others (specify)
 - iv. Cause Of Spill.
 - ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
 - ☒ Operational Error ☒ Others (specify).....
 - v. Visible Sign of Third Party Interference
 - ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
 - ☒ Others (specify).....



6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation..... NON — LEAK P. INT.

12. Time Investigation ended.....