



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NAOC
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 29/01/2017 ii. Date first reported: 29/01/2017
iii. Date of first investigation: 29/01/2017 iv. Spill Incidence No.: 2017/SAR/NL/007
v. Date of follow-up investigation:
vi. Time investigation started: 1:02 PM
vii. Estimated quantity spilled(bbls): NIL viii. Quantity Recovered: NIL
4. Site Details
i. Site/Location: 18" TERIDABA / BRASS PIPELINE AT OVEREGBENE
ii. State: BAYELSA iii. L.G.A.: SOUTHERN IJAW
iv. Spill Co-ordinates: N(m) 4° 29' 36.8"
E(m) 006° 04' 54.3"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
vi. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify).....
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
iv. Cause Of Spill.
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify).....



6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland
- ☐ Fish Pond
- ☐ Vegetation
- ☐ Fishing Net
- ☐ Surface water
- ☐ Venerable Objects
- ☐ Others (Specify)

ii. Nature of impact

- ☐ Oil stained vegetation
- ☐ Oil stained fishing nets
- ☐ Dead floating fishes
- ☐ Dead floating crabs
- ☐ Withering of vegetation
- ☐ Others (Specify)

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW
- ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
- ii.
- iii.
- iv.

(b) Land (Indicate area in m²)

- i.
- ii.
- iii.
- iv.

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation.....

JIV REPAIRS / DELIMITATION SURVEY COMPLETED
ON THE 29TH OF JANUARY 2017

12. Time Investigation ended..... 4:50 PM