



AN AREA VIEW OF THE NON-LEAK POINT



RIGHT OF WAY OF THE NON-LEAK POINT (ROW)

PHOTOGRAPH TAKEN DURING JIV



NON-LEAK POINT (4INCHES VALVE) INSTALLED



REPAIRED POINT