

1822713



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SPDC
2. Type of Complaint/Incident:
 - ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
 - ☐ Others (Specify) WATER LEAK
3. Incident Details
 - i. Date of Incident: 20/03/2017 ii. Date first reported: 21/03/2017
 - iii. Date of first investigation: 29-03-2017
 - iv. Date of follow-up investigation: 30-03-2017
 - v. Time investigation started: 12:10 HOURS
 - vi. Estimated quantity spilled: NIL
4. Site Details
 - i. Site/Location: 18" OKOLOMA KOM-KOM GAS PIPELINE
 - ii. Position of Spill/Leak: 4° 50' 30.41" 7° 10' 54.23"
 - iii. Spill area
 - ☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
 - ☐ Near shore ☐ Offshore ☐ Others (specify) LOOSE SOIL
 - iv. Structural Controls in Place
 - ☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) NIL
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
 - ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
 - ☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock ☒ 12 O' clock & 3 O' clock
 - ii. Type of Oil contaminant
 - ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
 - ☐ Others (specify) WATER
 - iii. Facility
 - ☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
 - ☐ Storage Tank ☐ Compressor Plant ☒ Others (specify) GAS PIPELINE
 - iv. Cause Of Spill
 - ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
 - ☐ Operational Error ☐ Others (specify)
 - v. Visible Sign of Third Party Interference
 - ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
 - ☐ Others (specify)

6. Impact of Incident

i Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)..... NIL.....

ii. Nature of impact

☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.... NIL.....

iii. Delineation of impacted area

☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

i. i.
 ii. ii.
 iii. iii.
 iv. iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....
.....
.....

12. Time investigation ended.....

13. Name and Signature of Participants

NOSDRA