

Photography's.



Picture showing the well cluster.



Showing K7s CCU removed.



Showing K7L CCU removed & leak point.



Showing CCU actuator removed.



Picture showing impacted area.



Pictures below showing some of the materials including bolts and nuts removed by vandals.