

2332755



## **NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**

### **JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: S.P.D.C.

2. Type of Complaint/Incident:

- ☒ Oil Pollution
 ☐ Fire/Explosion
 ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 25/04/2019      ii. Date first reported: .....  
 iii. Date of first investigation: 30/04/2019  
 iv. Date of follow-up investigation: .....  
 v. Time investigation started: .....  
 vi. Estimated quantity spilled: 20 Barrels

4. Site Details

- i. Site/Location: 12" MOR - OGALB PIPELINE AT KORM KORM  
 ii. Position of Spill/Leak: .....

iii. Spill area

- ☒ Land
 ☐ Swamp
 ☐ Freshwater
 ☐ Mangrove
 ☐ Coastline  
☒ Near shore
 ☐ Offshore
 ☐ Others (Specify) .....

iv. Structural Controls in Place

- ☐ Boom
 ☐ Trenches
 ☐ Bund Wall
 ☐ Sorbents
 ☐ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock
 ☐ 10 O'Clock
 ☐ 2 O'Clock
 ☐ 3 O'Clock  
☐ 4 O'Clock
 ☐ 5 O'Clock
 ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil
 ☐ Condensate
 ☐ Chemicals
 ☐ Refined Products  
☐ Others (Specify) .....

iii. Facility

- ☒ Pipeline
 ☐ Flow Line
 ☐ Wellhead
 ☐ Manifold
 ☐ Flow Station
 ☐ Rig  
☐ Storage Tank
 ☐ Compressor Plant  
☐ Others (Specify) .....

iv. Cause of Spill

- ☐ Corrosion
 ☐ Equipment Failure
 ☒ Third Party Interference
 ☐ Accident  
☐ Operational Error
 ☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks
 ☐ Drilled Holes
 ☐ Blasting
 ☐ Theft
 ☐ Acid  
☐ Others (Specify) INSTALLED BUNKERING VALVE

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable Objects ☐ Others (Specify) ..... *N/A*

### ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) ..... *N/A*

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

i. .... *KOM KORN* .....

ii. ....

iii. ....

iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

i. .... *0.04 ha* .....

ii. ....

iii. ....

iv. ....

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot    ☒ Boat    ☐ Aircraft

11. Remarks/Recommendation..... SPDC should intensify  
surveillance along the facilities.  
.....

12. Time Investigation ended.....