

Incident Number: 2017/LAR/056/095



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**

**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution  
☒ Others (Specify) CONDENSATE

3. Incident Details

- i. Date of Incident: 30-05-2017 ii. Date first reported: 30-05-2017  
iii. Date of first investigation: 01-06-2017  
iv. Date of follow-up investigation:                       
v. Time investigation started: 04:30 HRS  
vi. Estimated quantity spilled: 0.1 Barrels

4. Site Details

- i. Site/Location: OBIAFU 26S flowline AT Omokuy, ONELGA RIVER-STATE  
ii. Position of Spill/Leak: N05°24' 34.6" E006°34' 37.5"

iii. Spill area

- ☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline  
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☒ 3 O'Clock  
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☒ Condensate ☐ Chemicals ☐ Refined Products  
☐ Others (Specify)

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig  
☐ Storage Tank ☐ Compressor Plant  
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident  
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid  
☒ Others (Specify) WELDED 3" THREADED NIPPLE VALVE

Number: 2017/LAR/056/095

6. Impact of Incident

i. Property Damaged by the Incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Vegetable Crops ☐ Others (Specify) .....

ii. Nature of Incident

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
☐ Drifted fishing nets ☐ Withering of vegetation ☐ Others (Specify) .....

iii. Delineation of Incident Area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate area)

i. Omoku

(b) Land (Indicate area in m<sup>2</sup>)

i. 2910.279 m<sup>2</sup>

ii. ....

iii. ....

iv. ....

(c) Creek/Creek Mouth

☒ Tidal

☐ Non-tidal

| NAME | LOCATION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|-------------------|-----------------|----------------|
|      |                   |                 |                |
|      |                   |                 |                |
|      |                   |                 |                |
|      |                   |                 |                |

(d) Swamp

☒ Tidal

☐ Non-tidal

| NAME | LOCATION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|-------------------|-----------------|----------------|
|      |                   |                 |                |
|      |                   |                 |                |
|      |                   |                 |                |
|      |                   |                 |                |

(e) River

☒ Tidal

☐ Non-tidal

| NAME | LOCATION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|-------------------|-----------------|----------------|
|      |                   |                 |                |
|      |                   |                 |                |
|      |                   |                 |                |
|      |                   |                 |                |

(f) Shoreline/water

☒ Tidal

☐ Non-tidal

| NAME | LOCATION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|-------------------|-----------------|----------------|
|      |                   |                 |                |
|      |                   |                 |                |
|      |                   |                 |                |
|      |                   |                 |                |

Incident Number : 2017/LAR/056/095

8. Photograph/Map/Chart Ref.

☒ Still photographs

☐ Video coverage

☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot

☐ Boat

☐ Aircraft

11. Remarks/Recommendation

NAOC Should Improve Surveillance on her  
facility

12. Time Investigation ended.....