



Naoc

POST CLEAN UP JOINT INSPECTION REPORT

1.	SPILL REF. NO.:	2017/LAR/068/110		
2.	SPILL LOCATION:	EBEGORO GS GATE VALVE FLANGE AT THE WIRE LOCATION, OMOKU.		
3.	CO-ORDINATES:			
4.	DATE OF INSPECTION:	24/11/2017		
5.	SPILL DETAILS	DATE OF SPILL	CAUSE OF SPILL	QTY SPILLED
		16/6/2017	SABOTAGE	1.42BB
6.	DATE CLEAN UP COMMENCED:	17/6/17		
7.	CONTRACTOR:	IN-HOUSE		
8.	CONTRACT NO.:			
9.	CLEAN UP METHOD:	MECHANICAL ☒	MANUAL ☒	OTHERS ☒
	IF OTHERS, SPECIFY			
10.	CLEAN UP DURATION	DATE CLEAN UP COMPLETED	TOTAL DURATION OF CLEAN UP	
		17-6-2017	ONE	
11.	ANY INCIDENT DURING CLEAN UP?	YES ☐	NO ☒	
	IF YES, WHAT TYPE			
12.	ANY CASUALTY/INJURY?	YES ☐	NO ☒	
	IF YES, HOW WAS IT MANAGED?			
13.	VISUAL OBSERVATIONS: (TICK AS APPROPRIATE)			
	ANY OIL SHEEN ON WATER?	YES ☐	NO ☒	NA ☐
	ANY OIL STAIN ON VEGETATION?	YES ☐	NO ☒	NA ☐
	IS SOIL WET WITH OIL?	YES ☐	NO ☒	NA ☐
	ANY PATCHES OF OIL ON IMPACTED AREA?	YES ☐	NO ☒	NA ☐
	IS DISPOSAL OF OIL DEBRIS SATISFACTORY?	YES ☒	NO ☐	NA ☐
	WAS DISPERSANT APPLIED?	YES ☐	NO ☒	NA ☐

14. COMMUNITY ASSESSMENT:	VERY GOOD ☐	GOOD ☐	SATISFACTORY ☒	POOR ☐
---------------------------	------------------------------------	-------------------------------	--	-------------------------------



15. ANY SAMPLES COLLECTED?	YES ☒	NO ☐
----------------------------	---	-----------------------------

16. IF YES, WHAT TYPE	SOIL ☒	WATER ☐
-----------------------	--	--------------------------------

17. RECOMMENDATION:	Visual Observation. The site was properly cleaned and site passed. However the close out will be determined by the result of soil samples collected for laboratory analysis.
---------------------	--

18. CONCLUSION (INDICATE WHETHER CLEAN UP IS CERTIFIED AS):	SATISFACTORILY ☐	NOT SATISFACTORY ☐	POOR ☐
---	---	---	-------------------------------

INSPECTION TEAM:

NAOC	UHE DUNE OLWA	Site monitor		24/11/17
	NAME	DESIGNATION	SIGNATURE	DATE
DPR				
	NAME	DESIGNATION	SIGNATURE	DATE
NOSDRA	Godspower Isheke	SES		24/11/17
	NAME	DESIGNATION	SIGNATURE	DATE
SMENV	MARKIE TAYEN B	SES		24/11/17
	NAME	DESIGNATION	SIGNATURE	DATE
CONTRACTOR	IN-HOUSE			
	NAME	DESIGNATION	SIGNATURE	DATE
COMMUNITY	Emeka Agbateru	Landlord		24/11/17
	NAME	DESIGNATION	SIGNATURE	DATE
OTHERS	JOSEPH AZUBA	Officer in Charge		24/11/17
	NAME	DESIGNATION	SIGNATURE	DATE

SPILL SITE ASSESSMENT / SAMPLING JOINT REPORT

SPILL OF

2017/LAR/068/110

SPILL TYPE

EBEGORO 65 GATE VALVE FLANGE @ WELL LOC.

SPILL DATE

16/6/2017

(c) Date of spill:

(d) Cause of spill:

SABOTAGE


2. SITE DETAILS:

2.1 Media impacted:

(a) Soil



(c) Water body



(d) Others

2.2 Area of impact:

2.3 Distance of site from farmland, settlement and

ecosystem(s) (a) < 100m ☐ (b) < 1km

3. Visual inspection / observation:

Visually the site was properly cleaned and site passed. However the result of soil samples collected for laboratory analysis will determine the close out of the site.

sample collection:

Date of sample collection	Type of sample					Water sample / coordinate	Remarks
	Soil				Control soil sample (composite) / coordinate		
	Top (0-15cm)	Bottom (15-30cm)	Composite (0-30cm)	Coordinate of sampled point (soil)			
11/11/2017	✓	✓		05°21'33.3"	05°21'33.4"		
				006°39'01.1"	006°39'02.1"		
				05°21'33.4"			
				006°39'01.2"			
11/11/2017	✓	✓		05°21'33.3"			
				006°39'01.0"			
11/11/2017	✓	✓					

Number of soil samples collected: 6
Number of water samples collected: 1
Number of control soil samples collected: 2
Total number of samples collected: 8

Remarks/Recommendation:
Site passed and close out will be determined by the result of laboratory analysis.

LITERAINE OLIVER Sign: [Signature] Representing: NASE
Godspower Isike Sign: [Signature] Representing: NOSIRA, P.H.
Markie-Tamara Sign: [Signature] Representing: ASME NV, PH.
Joseph Azibato Sign: [Signature] Representing: Utermosteel
Emeka Agbakere Sign: [Signature] Representing: Landlord
Sign: Representing:

24th day of NOV 2017

OIL SPILL SITE JOINT INVESTIGATION VISIT ATTENDANCE SHEET

LOCATION/SPILL SITE: EBC 65 GATE VALVE FLANGE @ WELL LOC.
 SPILL REF. NO: 2017/LAR/068/110
 DATE OF SPILL: 16/6/2017
 DATE OF INSPECTION: 24/11/2017

S/no.	Name	Company / Organization / Community	Signature / Date
1	ITHEBUKE OLIVER	NAOC	[Signature] 24/11/17
2	MANKIE-TANEN B	RSMENU	[Signature] 24/11/17
3	Emeka Agbakere	landlord	[Signature] 24/11/17
4	Godspower Ikheke	NOSDRA	[Signature] 24/11/17
5	JOSEPH KUBOJO	HERMOSITE	[Signature] 24/11/17

Name of Responsible: ITHEBUKE OLIVER Signature: [Signature] 24/11/17