



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY (NAOC)
2. Type of Complaint/Incident:
☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 31.03.2017 ii. Date first reported: 31.03.2017
 - iii. Date of first investigation: 31.03.2017 iv. Spill Incident No: 2017/SAR/30
 - v. Date of follow-up investigation:
 - vi. Time investigation started: 10:28AM
 - vii. Estimated quantity spilled(bbls): 29BBLs viii. Quantity Recovered: NIL
4. Site Details
 - i. Site/Location: 14" OGBOMBIRI/TEBIDABA PIPELINE AT OLUGBOBORO
 - ii. State: BATELSA iii. L.G.A: SILGA
 - iv. Spill Co-Ordinates: N(m) N04° 38' 44.0"
E(m) E005° 57' 22.7"
 - v. Spill area
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (specify).....
 - iv. Structural Controls in Place
☒ Boom ☒ Trenches ☒ Bund wall ☒ Sorbents ☒ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☒ 12 O' Clock ☒ 10 O' Clock ☒ 2 O' Clock ☒ 3 O' Clock
☒ 4 O' Clock ☒ 5 O' Clock ☒ 6 O' Clock
 - ii. Type of Oil contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (specify)
 - iii. Facility
☒ Pipeline ☒ Flow line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant ☐ Others (specify).....
 - iv. Cause of Spill
☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (specify).....

6. Impact of Incident

i Properties impacted by the incident

☒ Farmland ☐ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others.....

iii. Delineation of impacted area

☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

☒ Crops ☒ Fish Farm/ Pond ☒ Fishing Net ☒ Makeshift
☒ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☒ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

9. **Samples taken**.....

10. **Investigation carried out by**

☐ Foot ☒ Boat ☐ Aircraft

11. **Remarks/Recommendation**.....

Surveillance should be kept up to prevent further incident. Urgent clean up of impacted area is required as soon as possible. Also line needs to be repaired.

12. **Time investigation ended**.....

3:30 PM