

2017 | NL | LAR | 015



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) NON - LEAK

3. Incident Details

- i. Date of Incident: 23-06-17 ii. Date first reported: 23-06-17
iii. Date of first investigation: 29-06-17
iv. Date of follow-up investigation: —
v. Time investigation started: 14 00HRS
vi. Estimated quantity spilled: —

4. Site Details

- i. Site/Location: Ebochi 25 flareline close To Ebochi 8 Location
ii. Position of Spill/Leak: N 05° 26' 58.6" E 086° 40' 06.2"
iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☒ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Property Damaged by the Incident

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water

☐ Vegetables/Crops ☐ Others (Specify) N/A

ii. Nature of Incident

☐ Oil spill on vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating webs ☐ Withering of vegetation ☐ Others (Specify) N/A

iii. Define the Incident Area

☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate area in m²)

i.

ii.

iii.

iv.

b) Land (Indicate area in m²)

i.

ii.

iii.

iv.

(c) Creek/Creek Mouth ☐ Tidal ☐ Non-tidal

NAME	LOCATION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	LOCATION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	LOCATION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/waterway ☐ Tidal ☐ Non-tidal

NAME	LOCATION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs

☐ Video coverage

☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot

☐ Boat

☐ Aircraft

11. Remarks/Recommendation.....

NAOC should improve Surveillance
and effect Repair immediately