

2017/LAR/GLI/012



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NADOL

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) GAS Emission

3. Incident Details

- i. Date of Incident: 23-06-2017 ii. Date first reported: 23-06-2017
iii. Date of first investigation: 29-06-2017
iv. Date of follow-up investigation: —
v. Time investigation started: 1400HRS
vi. Estimated quantity spilled: —

4. Site Details

- i. Site/Location: EBoche JT flowline close To EBoche 8 location
ii. Position of Spill/Leak: N 26° 58' 5" E 006° 40' 05" 1"
iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify).....

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock ☒ 10-5 o'clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) GAS

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☐ Surface water
☐ Vegetable Crops ☐ Others (Specify) **N/A**

ii. Nature of Impact

- ☐ Oil spill contamination ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating fish ☐ Withering of vegetation ☐ Others (Specify) **N/A**

iii. Delimited Impact Area

- ☐ Within Company's facility ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate impact)

- i.
 ii.
 iii.
 iv.

(b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creeks

☒ Tidal

☐ Non-tidal

NAME	LOCATION OF	CK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☒ Tidal

☐ Non-tidal

NAME	LOCATION OF	CK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☒ Tidal

☐ Non-tidal

NAME	LOCATION OF	CK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☒ Tidal

☐ Non-tidal

NAME	LOCATION OF	CK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs

☐ Video coverage

☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot

☐ Boat

☐ Aircraft

11. Remarks/Recommendation.....

NAOC Should Improve Surveillance
and Effect Repair Immediately.

12. Time Investigation on 10/1.....

13. Name and Signature of Participants