

2017/NL/LAR/016



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NADU

2. Type of Complaint/Incident:

☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify) NON - LEAK

3. Incident Details

i. Date of Incident: 23-06-2017 ii. Date first reported: 23-06-2017

iii. Date of first investigation: 29-06-2017

iv. Date of follow-up investigation:

v. Time investigation started: 1400HRS

vi. Estimated quantity spilled:

4. Site Details

i. Site/Location: Ebochi, 4L flowline close To Ebochi 8 location

ii. Position of Spill/Leak: N05° 26' 58.8" E 086° 40' 05.6"

iii. Spill-area

☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 O'Clock ☐ 10 O'Clock ☒ 2 O'Clock ☐ 3 O'Clock

☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (Specify) GAS

iii. Facility

☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify)

iv. Cause of Spill

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

☐ Hackney Marks ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (Specify)

6. Impact of Incident

i. Properties affected by the incident

- ☐ Pond/pond
☐ Fish Pond
☐ Vegetation
☐ Fishing Net
☐ Surface water
☐ Vegetative Objects
☐ Others (Specify)

N/A

ii. Nature of Incident

- ☐ Oil spilled on vegetation
☐ Oil stained fishing nets
☐ Dead floating fishes
☐ Dead floating plants
☐ Withering of vegetation
☐ Others (Specify)

N/A

iii. Define the affected area

- ☐ Within Company's facility
☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Land (Indicate area in m²)

- i.
 ii.
 iii.
 iv.

(c) Creek/Creek

Tidal

☐ Non-tidal

NAME	LOCATION OF	CK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

Tidal

☐ Non-tidal

NAME	LOCATION OF	CK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

Tidal

☐ Non-tidal

NAME	LOCATION OF	CK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

Tidal

☐ Non-tidal

NAME	LOCATION OF	CK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

NAOC should improve surveillance
and effect repair on her pipe

12. Time Investigation started.....