

Incident Number: 2017/LAR/086



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NODC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 30-07-2017 ii. Date first reported: 30-07-2017
iii. Date of first investigation: 31-07-2017
iv. Date of follow-up investigation:
v. Time investigation started:
vi. Estimated quantity spilled: 4.5 BBLs

4. Site Details

- i. Site/Location: EBEGPO 12L Flowline, Onok, ONTLEGA
ii. Position of Spill/Leak: N 05° 28' 11.1" E 006° 39' 09.8"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock ☒ 12 - 3 O'clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hack saw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Damaged by the Incident

- ☐ Farm Land ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Vegetable Crops ☐ Others (Specify) **N/A**

ii. Nature of Incident

- ☐ Oil Spill/Discharge ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating seals ☐ Withering of vegetation ☐ Others (Specify) **N/A**

iii. Delimited Incident Area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate number)

i. **E. Becopo**

b) Land (Indicate area in m²)

i. **1874.19**

ii.

iii.

iv.

(c) Creek/Creek Mouth ☐ Tidal ☐ Non-tidal

NAME	LOCATION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	LOCATION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	LOCATION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	LOCATION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... *NAOC Should Improve Surveillance on her facility*