



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: S P D C

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....

3. Incident Details

- i. Date of Incident: 4/12/13 ii. Date first reported: 5/12/13
iii. Date of first investigation: 6/12/13
iv. Date of follow-up investigation: NIL
v. Time investigation started: 2.30 PM
vi. Estimated quantity spilled: 1 barrel

4. Site Details

- i. Site/Location: FORCADO SPM2
ii. Position of Spill/Leak: ME 304435, 129382 MN (SPM1) ME 305240, 129193 SPM2
iii. Spill area
☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Nearshore ☒ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify)..... NONE
v. The state of the spilled oil
Fresh ☒ Oil ☐ Weathered ☐ emulsified ☐ others (specify).....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock

} NOT APPLICABLE

ii. Type of Oil contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)

iii. Facility

- ☐ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station Rig ☐
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify) S.P.M.

iv. Cause Of Spill.

- ☐ Corrosion ☒ Equipment Failure ☐ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify)..... NOT APPLICABLE

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others... **NOT APPLICABLE**

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i. **NOT APPLICABLE**
ii.
iii.
iv.

b) Land (indicate area in m²)

- i.
ii.
iii.
iv.

b) Creeks/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9/7

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken..... NOT APPLICABLE

10. Investigation carried out by

☐ Foot ☐ Boat ☒ Aircraft

11. Remarks/Recommendation. (1) IDENTIFY EXACT EQUIPMENT
THAT CAUSED THE SPILL (2) EFFECT REPAIR ON
8 PM 2

12. Time investigation ended 4:50 PM