

2014/LAR/006/019



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) Gaseous Emission

3. Incident Details

- i. Date of Incident: 8/1/2014 ii. Date first reported: 8/1/2014
iii. Date of first investigation: 8/1/2014
iv. Date of follow-up investigation:
v. Time investigation started: 15.00 hrs
vi. Estimated quantity spilled: NIL (Gaseous Emission)

4. Site Details

- i. Site/Location: Ebocha field gas network flowline @ Omoku.
ii. Position of Spill/Leak: N05°27'00.1" E006°37'39.0"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock ☐ 10 0'Clock ☒ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock ☒ 10'clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☒ Others (Specify) Gaseous Emission

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i Properties impacted by the incident

☐Farmland ☐Fish Pond ☒Vegetation ☐Fishing Net ☐Surface water
☐Venerable Objects ☐Others (specify).....

ii. Nature of impact

☐Oil stained vegetation ☐Oil stained fishing nets ☐Dead floating fishes
☐Dead floating crabs ☒Withering of vegetation ☐Others.....

iii. Delineation of impacted area

☐Within Company's facility/ROW ☐Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

i.
ii.
iii.
iv.

b) Land (indicate area in m²)

i.
ii.
iii.
iv.

b) Creeks/Creek lets

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

9. **Samples taken**.....

10. **Investigation carried out by**

☒ Foot ☐ Boat ☐ Aircraft

11. **Remarks/Recommendation**.....

Immediate repair of affected pipe.
Increase in surveillance.

12. **Time investigation ended**.....