



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: PPM.C
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
 - i. Date of Incident: 20/10/2013 ii. Date first reported: 21/10/2013
 - iii. Date of first investigation: 11/12/2013
 - iv. Date of follow-up investigation:
 - v. Time investigation started: 2:30 pm
 - vi. Estimated quantity spilled: NIL
4. Site Details
 - i. Site/Location: KM 75.6 AAuma KAD - JUS Axes
 - ii. Position of Spill/Leak: N10:16227° E002:05740 Z 730m
 - iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
 - iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
 - i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
 - ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☒ Refined Products
☐ Others (specify)
 - iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
 - iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
 - v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify) no impact

ii. Nature of impact

☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others

iii. Delineation of impacted area

☒ Within Company's facility/POW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

i. Adams Village

i. _____

ii. _____

ii. _____

iii. _____

iii. _____

iv. _____

iv. _____

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken... *None*

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation

*Clean up of the impacted
and the vandalized pipeline should
be immediately buried.*

12. Time investigation ended

2:58pm

13. Name and Signature of Participants

❖ NOSDRA

1. *Shutu Madani Sst. 12/12/2013*
2. *Titus Akpan 12/12/2013*
- 3.

❖ DPR

- 1.
- 2.
- 3.

❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY

- 1.
- 2.
- 3.

*RPMC
Shuaibu Musa
16/12/13*

❖ COMMUNITY

- 1.
- 2.
- 3.