



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: PPMC
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 31st Dec, 2011 ii. Date first reported: 21st December, 2011
iii. Date of first investigation: 18th January, 2012
iv. Date of follow-up investigation:.....
v. Time investigation started: 2:55pm
vi. Estimated quantity spilled: Unknown
4. Site Details
i. Site/Location: KM 73 Anini Village (Kwara)
ii. Position of Spill/Leak: N 08. 4458° E 006. 56 4430°
iii. Spill area
☒ Land ☐ Swamp ☒ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
iv. Structural Controls in Place
☒ Boom ☐ Trenches ☐ Bund wall ☒ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
- iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify).....
- iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
- v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. KM 73 Anni Kwato
 ii. Village
 iii.
 iv.

b) Land (indicate area in m²)

- i. 500m²
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation *Clean up and remediation
Should be carried out immediately.*

12. Time investigation ended *3:34pm*

13. Name and Signature of Participants

❖ NOSDRA

1. *Idi Yusuf Ali*

2. *Shirly Malau* *18-01-2012*

3.

❖ DPR

1.

2.

3.

❖ STATE MINISTRY OF ENVIRONMENT

1.

2.

3.

❖ LOCAL GOVERNMENT COUNCIL

1.

2.

3.

❖ COMPANY

1. *Irene M. J. [Signature]*

2.

3.

❖ COMMUNITY

1.

2.

3.