

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company PPMC
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)
3. Incident Details
i. Date of Incident: 23/07/13 ii. Date first reported: 24/07/2013
iii. Date of first investigation: 12/09/2013
iv. Date of follow-up investigation:
v. Time investigation started: 11:10 am
vi. Estimated quantity spilled:
4. Site Details
i. Site/Location: Km 31 Wela village 120m, Gurara L.G.A
ii. Position of Spill/Leak: N09.28115°, E006.95615°, Z. 246m
iii. Spill area
☒ Land ☐ Swamp ☒ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify)
iv. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify)
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☒ Refined Products
☒ Others (specify) AGO
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
iv. Cause Of Spill
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify)

6. Impact of Incident

i. Properties impacted by the incident

☒ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water

☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☒ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

i.

i.

ii.

ii.

iii.

iii.

iv.

iv.

b) Creeks/Creeklets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft




11. Remarks/Recommendation.....

The Impacted site should be remediated and the exposed pipe have covered immediately.

12. Time investigation ended..... 11:35 am

13. Name and Signature of Participants

❖ NOSDRA

- 1. Mutshew Alexander D. 
- 2. Hudson Usman 
- 3. RZEH Vincent Sidney 

❖ DPR

- 1.
- 2.
- 3.



❖ STATE MINISTRY OF ENVIRONMENT

- 1.
- 2.
- 3.

❖ LOCAL GOVERNMENT COUNCIL

- 1.
- 2.
- 3.

❖ COMPANY PPMC

- 1. Ouyechobwa T.I.  12/09/13
- 2. A. H. Adomg  12/09/2013
- 3.

❖ COMMUNITY

- 1.
- 2.
- 3.