



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify) Condense

3. Incident Details

- i. Date of Incident: 9/1/14 ii. Date first reported: 29/1/14
iii. Date of first investigation: 19/01/14
iv. Date of follow-up investigation: _____
v. Time investigation started: 15 hrs
vi. Estimated quantity spilled: 10 litres

4. Site Details

- i. Site/Location: DBF 2SL WELLHEAD LOCATION AT OMAKU
ii. Position of Spill/Leak: N 05° 24' 52.2" E 006 35 43.9"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify) _____

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) Nil

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☒ 6 0'Clock

ii. Type of Oil Contaminant

- ☐ Crude Oil ☒ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) _____

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify) _____

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify) _____

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) One litre Hacksaw (burr)

d. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) *Nil*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) *nil*

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

/. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

(Impacted area 4m²)

- ii.
iii.
iv.

(c) Creek/Creek jets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

9. **Samples taken**.....

10. **Investigation carried out by**

☒ Foot ☐ Boat ☐ Aircraft

11. **Remarks/Recommendation**..... *NOAC should improve on
flowline surveillance*.....

12. **Time investigation ended**.....