



## NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV Form is to be completed and signed by all participating parties in the field

1. Company: SPDC
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify).....
3. Incident Details  
i. Date of Incident: 07/11/13    ii. Date first reported: 08/11/13  
iii. Date of first investigation: 14/11/13  
iv. Date of follow-up investigation:.....  
v. Time investigation started: 1300 HRS  
vi. Estimated quantity spilled: 0.1 BBLs
4. Site Details  
i. Site/Location: BENESIDE WELL 17 FLDWLING RISER (EKEREMOR LGA BAYELSA STATE)  
ii. Position of Spill/Leak: 05 00 28.5N, 005 41 29.8E  
iii. Spill area  
☐ Land    ☒ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (specify).....  
iv. Structural Controls in Place  
☒ Boom    ☐ Trenches    ☐ Bund wall    ☐ Sorbents    ☐ Others (specify).....
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☐ 12 O' Clock    ☐ 10 O' Clock    ☐ 2 O' Clock    ☒ 3 O' Clock  
☐ 4 O' Clock    ☐ 5 O' Clock    ☐ 6 O' Clock  
ii. Type of Oil contaminant  
☒ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☐ Others (specify) .....
- iii. Facility  
☐ Pipeline    ☐ Flow line    ☒ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant    ☐ Others (specify) .....
- iv. Cause Of Spill.  
☐ Corrosion    ☒ Equipment Failure    ☐ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (specify).....
- v. Visible Sign of Third Party Interference  
☐ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☐ Theft    ☐ Acid  
☐ Others (specify)..... N/A

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland   ☐ Fish Pond   ☐ Vegetation   ☐ Fishing Net   ☒ Surface water  
☐ Venerable Objects   ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
☐ Dead floating crabs   ☐ Withering of vegetation   ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW   ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops   ☐ Fish Farm/ Pond   ☐ Fishing net   ☐ Makeshift  
☐ Permanent   ☐ Others ..... *NIL*

8. Extent of Impact

a) Community (indicate name)

- i. *NIL*  
ii. *NIL*  
iii. *NIL*  
iv. *NIL*

b) Land (indicate area in m<sup>2</sup>)

- i. ....  
ii. ....  
iii. ....  
iv. ....

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

c) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

d) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

e) Shoreline/water

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

## 9. Photograph/Map/Chart Ref.

☒ Still photographs   ☒ Video coverage   ☐ Mapping

10. Samples taken.....

## 11. Investigation carried out by

☐ Foot   ☒ Boat   ☐ Aircraft

12. Remarks/Recommendation.....

IMMEDIATE REPAIR OF THE  
WELL-HEAD AND CONSIDERING THE VERY <sup>LIGHT</sup> SHEEN

OBSERVED, IT IS ~~ADVISED~~ THAT NATURE SHOULD BE ALLOWED  
TO TAKE CARE OF IT.

13. Time investigation ended ..... 1620 HRS