



981

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: SPDC (SHELL PETROLEUM DEV. COMP.)
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 15/02/14 ii. Date first reported: 16/02/14
iii. Date of first investigation: 18/02/14 iv. Spill Incidence No.: 1122345
v. Date of follow-up investigation:/...../..... NOT APPLICABLE
vi. Time investigation started: 11:51am
vii. Estimated quantity spilled(bbls): 566L viii. Quantity Recovered: NILL
4. Site Details
i. Site/Location: JB HELL CLUSTER ISI ESTUARY
ii. State: DELTA iii. L.G.A.: BURUTU (BURUTU)
iv. Spill Co-ordinates: N(m) 05° 22' 59.5" N
E(m) 005° 17' 39.3" E
v. Spill area
☐ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☒ Offshore ☐ Others (specify).....
vi. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) NOT APPLICABLE
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☐ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock NOT APPLICABLE
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
iii. Facility
☐ Pipeline ☐ Flow line ☒ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
iv. Cause Of Spill.
☐ Corrosion ☐ Equipment Failure ☐ Third Party Interference ☐ Accident
☒ Operational Error ☐ Others (specify).....
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) NOT APPLICABLE

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others..... **NONE**

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others **NONE**

8. Extent of Impact

a) Community (indicate name)

i. **OGULAGHA KINGDOM (ESTUARY)**

ii.

iii.

iv.

b) Land (indicate area in m²)

i.

ii.

iii.

iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

983

9. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

10. Samples taken..... NILL

11. Investigation carried out by

☐ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommedation..... ALL SHORE LINES AND
SURFACE WATER SHOULD BE CLEANED
AS APPLICABLE

13. Time investigation ended 3.00 PM