



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 8/02/14 ii. Date first reported: 12/02/14
iii. Date of first investigation: 12/02/14
iv. Date of follow-up investigation:
v. Time investigation started:
vi. Estimated quantity spilled: 15L

4. Site Details

- i. Site/Location: 28" Nkpoka - Bomu pipeline at Alets.
ii. Position of Spill/Leak: 12 O'clock position.

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) N/A

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) Three (3) numbers of 2" valve was installed

at 12 o'clock position for oil theft (Not drilled) as at the time of Jiv.

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)..... None

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others..... NA

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. Aleto
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

9. **Samples taken**..... *NA.*

10. **Investigation carried out by**

☒ Foot ☐ Boat ☐ Aircraft

11. **Remarks/Recommendation**.....

*Clamping of the affected
pipeline should be carried out immediately*

12. **Time investigation ended**.....