



## NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

### JOINT INVESTIGATION VISIT (JIV) FORM

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: NAOC

2. Type of Complaint/Incident:

- ☒ Oil Pollution     
 ☒ Fire/Explosion     
 ☒ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 08-12-2017      ii. Date first reported: 08-12-2017  
 iii. Date of first investigation: 15-12-2017  
 iv. Date of follow-up investigation: .....  
 v. Time investigation started: 1520HRS  
 vi. Estimated quantity spilled: N/A

4. Site Details

- i. Site/Location: OBRIKOM TT FLOWLINE OMOKU ONELGA RIVERS STATE  
 ii. Position of Spill/Leak: N05°23'10.3" E006°37'49.9"

iii. Spill area

- ☒ Land     
 ☒ Swamp     
 ☒ Freshwater     
 ☒ Mangrove     
 ☒ Coastline  
☒ Near shore     
☒ Offshore     
☒ Others (Specify) .....

iv. Structural Controls in Place

- ☒ Boom     
 ☒ Trenches     
 ☒ Bund Wall     
 ☒ Sorbents     
☒ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock     
☒ 10 0'Clock     
☒ 2 0'Clock     
☒ 3 0'Clock  
☒ 4 0'Clock     
☒ 5 0'Clock     
☒ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil     
☒ Condensate     
☒ Chemicals     
☒ Refined Products  
☐ Others (Specify) ..... G.A.S.

iii. Facility

- ☒ Pipeline     
☒ Flow Line     
☒ Wellhead     
☒ Manifold     
☒ Flow Station     
☒ Rig  
☒ Storage Tank     
☒ Compressor Plant  
☒ Others (Specify) .....

iv. Cause of Spill

- ☒ Corrosion     
☒ Equipment Failure     
☒ Third Party Interference     
☒ Accident  
☒ Operational Error     
☒ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks     
☒ Drilled Holes     
☒ Blasting     
☒ Theft     
☒ Acid



## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland   ☒ Fish Pond   ☒ Vegetation   ☒ Fishing Net   ☒ Surface water  
☒ Venerable Objects   ☒ Others (Specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation   ☒ Oil stained fishing nets   ☒ Dead floating fishes  
☒ Dead floating crabs   ☒ Withering of vegetation   ☒ Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW   ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

- i. ....  
ii. ....  
iii. ....  
iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

- i. ....  
ii. ....  
iii. ....  
iv. ....

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☒ Mapping

9. Samples taken..... N/A .....

10. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

11. Remarks/Recommendation. REPAIRS WAS DONE IMMEDIATELY AFTER  
NAOC SHOULD IMPROVE SURVEILLANCE ON THE FACILITY  
JIV

12. Time Investigation ended. 1600HRS .....