

Inc. No. 2042332

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

Company:

SPDC

Type of Complaint Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident 19/03/18 ii. Date first reported
iii. Date of first investigation 30/03/18
iv. Date of follow-up investigation
v. Time investigation started 10:40 hrs
vi. Estimated quantity spilled nil (no leaking)

4. Site Details

- i. Site/Location (old) 20" Kolo Creek - Remuekpe T/K @ Odan
ii. Position of Spill/Leak: N 04° 56' 17.1 E 006° 29' 57.7

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify) Seasonal Swamp

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (Specify) illegal connection for oil theft, was seen installed on p/c.

6. Impact of Incident

i. Properties Impacted by the Incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (Specify) *NA/A*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) *NA/A*

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW *NA/A*

7. Extent of Impact

(a) Community (Indicate name)

i. *ODAN*

ii.

iii.

iv.

(b) Land (Indicate area in m²)

i.

ii.

iii.

iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten arrow]</i>	<i>[Handwritten arrow]</i>	<i>[Handwritten arrow]</i>	<i>[Handwritten arrow]</i>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten arrow]</i>	<i>[Handwritten arrow]</i>	<i>[Handwritten arrow]</i>	<i>[Handwritten arrow]</i>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten arrow]</i>	<i>[Handwritten arrow]</i>	<i>[Handwritten arrow]</i>	<i>[Handwritten arrow]</i>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>[Handwritten arrow]</i>	<i>[Handwritten arrow]</i>	<i>[Handwritten arrow]</i>	<i>[Handwritten arrow]</i>

8. Photograph/Map/Chart Ref.

☒ Still photographs

☐ Video coverage

☒ Mapping

9. Samples taken

21/A

10. Investigation carried out by

☒ Foot

☐ Boat

☐ Aircraft

11. Remarks/Recommendation

Improved security is needed @ Odau.
There is a need for military action to deal with
these w/ launching activities @ Odau. Further need

12. Time investigation ended

17.00 hrs

13. Name and Signature of Participant