

2018/LAR/042



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NACC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 29/3/2018 ii. Date first reported: 29/3/2018  
iii. Date of first investigation: 30/3/2018  
iv. Date of follow-up investigation: .....  
v. Time investigation started: 1242 HRS  
vi. Estimated quantity spilled: .....

4. Site Details

- i. Site/Location: ALWISO 2T FLOW LINE AT ALIGU ONELGA RIVERS STATE  
ii. Position of Spill/Leak: N05°19'44"-S E006°37'42"-E

iii. Spill area

- ☐ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline  
☒ Near shore ☒ Offshore ☒ Others (Specify) .....

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock ☒ 10 O'Clock ☒ 2 O'Clock ☒ 3 O'Clock  
☒ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock 4-7 o'clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products  
☒ Others (Specify) .....

iii. Facility

- ☒ Pipeline ☐ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig  
☒ Storage Tank ☒ Compressor Plant  
☐ Others (Specify) .....

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident  
☐ Operational Error ☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid  
☒ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
 ☒ Others (Specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
☒ Dead floating crabs  
 ☒ Withering of vegetation  
 ☒ Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW  
 ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

- i. ....  
 ii. ....  
 iii. ....  
 iv. ....

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs   ☒ Video coverage   ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot   ☒ Boat   ☒ Aircraft

11. Remarks/Recommendation

AOC should ensure proper  
check of the integrity of the facility  
repaired.

12. Time Investigation ended.....

13. Name and Signature of Participants