



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV Form is to be completed and signed by all participating parties in the field*

1. Company: NNPC-PPMC.
2. Type of Complaint/Incident:  
☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify).....
3. Incident Details  
i. Date of Incident: 9<sup>th</sup> Feb, 2014    ii. Date first reported: 10<sup>th</sup> Feb, 2014  
iii. Date of first investigation: 11<sup>th</sup> Feb, 2014  
iv. Date of follow-up investigation: 11<sup>th</sup> Feb, 2014  
v. Time investigation started: 1130 Hrs.  
vi. Estimated quantity spilled: 165,000 litres
4. Site Details  
i. Site/Location: IJEGBUN-IMORE.  
ii. Position of Spill/Leak: SWAMP.  
iii. Spill area  
☐ Land    ☒ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (specify).....  
iv. Structural Controls in Place  
☐ Boom    ☒ Trenches    ☐ Bund wall    ☒ Sorbents    ☐ Others (specify).....
5. Circumstances Around Spill Point  
i. Visual observation of Hole Position  
☐ 12 O' Clock    ☒ 10 O' Clock (POINT III)    ☐ 2 O' Clock    ☒ 3 O' Clock (POINT II)  
☐ 4 O' Clock    ☐ 5 O' Clock    ☒ 6 O' Clock (POINT I)  
ii. Type of Oil contaminant  
☐ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☒ Others (specify) AGO  
iii. Facility  
☒ Pipeline    ☐ Flow line    ☐ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant    ☐ Others (specify).....  
iv. Cause Of Spill  
☐ Corrosion    ☐ Equipment Failure    ☒ Third Party Interference (POINT II & III)    ☒ Accident (POINT I)  
☐ Operational Error    ☐ Others (specify).....  
v. Visible Sign of Third Party Interference  
☐ Hacksaw Marks    ☒ Drilled Holes    ☐ Blasting    ☐ Theft    ☐ Acid  
☐ Others (specify).....