

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

Oil sheen was observed in the swamp. It is recommended
that a post-impact assessment (PIA) should be carried out in the site.

12. Time investigation ended 1440HRS. (Security personnel and marker-post should
be posted in the site)