

2013/SAR/468/782



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 26/12/13 ii. Date first reported: 26/12/13
iii. Date of first investigation: 27/12/13
iv. Date of follow-up investigation:
v. Time investigation started: 1040 HRS
vi. Estimated quantity spilled: 0.03 BBLs

4. Site Details

- i. Site/Location: 18" TEBIDABA/BRASS P/L @ KALATORU
ii. Position of Spill/Leak: NO4°32'34.4" E005°57'31.2"

iii. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify) 3" VALVE INSTALLED BY UNKNOWN PERSONS

6. Impact of Incident

- i Properties impacted by the incident
- ☐Farmland ☐Fish Pond ☐Vegetation ☐Fishing Net ☐Surface water
- ☐Venerable Objects ☐Others (specify).....N/A.....
- ii. Nature of impact
- ☐Oil stained vegetation ☐Oil stained fishing nets ☐Dead floating fishes
- ☐Dead floating crabs ☐Withering of vegetation ☐Others.....N/A.....
- iii. Delineation of impacted area
- ☒Within Company's facility/ROW ☐Outside Company's facility/ROW

7. Extent of Impact

- a) Community (indicate name)
- i. KALATOU.....
- ii.
- iii.
- iv.
- b) Land (indicate area in m²)
- i.
- ii.
- iii.
- iv.
- b) Creeks/Creek lets ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- c) Swamp ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- d) River ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

- e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... N/A

10. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation..... JW/REPAIRS AND DELIMITATION

SURVEY COMPLETED ON 27 THE SAME DAY.

IN HOUSE CLEAN UP.

12. Time investigation ended..... 1414 HRS