



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NAOC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 02-03-2014 ii. Date first reported: 02-03-2014
iii. Date of first investigation: 02-03-2014
iv. Date of follow-up investigation:
v. Time investigation started: 11:30 AM
vi. Estimated quantity spilled: 0.06 BARRELS (10 LITRES)

4. Site Details

- i. Site/Location: 18" TEBIDABA/BRASS PIPELINE AT KAMBORO
ii. Position of Spill/Leak: N04° 32' 52.4" E006° 56' 27.1"

iii. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. KAMPBORD
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

N/A

10. Investigation carried out by

☐ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation.....

Repairs / Delimitation Survey Completed
As at the time of JIV. The team mapped up the crude,
hence no clean up is required.

12. Time investigation ended.....

12:58 PM