



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: Shell Petroleum Development Company
2. Type of Complaint/Incident:
☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☒ Others (Specify) Incident
3. Incident Details
i. Date of Incident: 14/03/2014 ii. Date first reported: 14/03/2014
iii. Date of first investigation: 16/03/2014 iv. Spill Incidence No.: 1139786
v. Date of follow-up investigation:
vi. Time investigation started: 1:35pm
vii. Estimated quantity spilled(bbls): N/A viii. Quantity Recovered: None
4. Site Details
i. Site/Location: 20" Ofumara-Escravos Pipeline @ Ogbegungun
ii. State: Delta iii. L.G.A.: Warri South West L/G
iv. Spill Co-ordinates: N(m) 05° 37' 14.3"
E(m) 005° 10' 06.9"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify)
vi. Structural Controls in Place
☐ Boom ☐ Trenches ☐ Bund wall ☐ Sorbents ☐ Others (specify) None
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☒ Others (specify) None
iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
iv. Cause Of Spill.
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify)
v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (specify) 3" Valve on pipeline

6. Impact of Incident

i. Properties impacted by the incident

Not Applicable

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others..... None

iii. Delineation of impacted area

No Impact.

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

- i.
ii.
iii.
iv.

- i.
ii.
iii.
iv.

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
///	///	///	///

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
///	///	///	///

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
///	///	///	///

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
///	///	///	///

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

None

11. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

12. Remarks/Recommendation.....

(i) There was no impact.
(ii) No visible sign of oil on vegetation

13. Time investigation ended

2.15pm.