



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY LIMITED

2. Type of Complaint/Incident:

- ☐ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 2/6/2014 ii. Date first reported: 3/6/2014
iii. Date of first investigation: 3/6/2014
iv. Date of follow-up investigation:
v. Time investigation started: 14:45 HRS
vi. Estimated quantity spilled: (3) 0.06 BBL & (5) 0.01 BBL

4. Site Details

- i. Site/Location: EBOCHA 3LS FLOWLINE OFF NOONIRD, ALONG EBOCHA FERRY RD
ii. Position of Spill/Leak: (1) N 05° 26' 57.3" (2) N 05° 27' 01.4" (3) N 05° 27' 02.8" (4) N 05° 27' 06.0"
E 006° 40' 48.7" E 006° 40' 56.2" E 006° 40' 58.7" E 006° 41' 04.6"
iii. Spill area (5) N 05° 27' 07.4"
E 006° 41' 07.5"
☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

- i. Visual observation of Hole Position (1) 1-4 Clock
(2) ☒ 12 0' Clock ☒ 10 0' Clock ☒ 2 0' Clock ☒ 3 0' Clock
☒ 4 0' Clock ☒ 5 0' Clock (3) ☒ 9 0' Clock (4) 11-12 0' Clock
(5) 1-3 0' Clock
ii. Type of Oil Contaminant
☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify)

6. Impact of Incident

i Properties impacted by the incident

- ☒Farmland ☒Fish Pond ☒Vegetation ☒Fishing Net ☒Surface water
☒Venerable Objects ☒Others (specify).....

ii. Nature of impact

- ☒Oil stained vegetation ☒Oil stained fishing nets ☒Dead floating fishes
☐Dead floating crabs ☒Withering of vegetation ☒Others.....

iii. Delineation of impacted area

- ☒Within Company's facility/ROW ☒Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

b) Land (indicate area in m²)

- i. i.
ii. ii.
iii. iii.
iv. iv.

b) Creeks/Creek lets ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River ☐Tidal ☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... NIL

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation... EFFECT REPAIRS AND INTENSIVE
SURVEILLANCE ON THE FACILITY TO AVOID FUTURE OCCURRENCE.

12. Time investigation ended..... 16:00 HRS