



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: NAOC

2. Type of Complaint/Incident:

- ☐ Oil Pollution      ☐ Fire/Explosion      ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 07/05/2014      ii. Date first reported: 07/05/2014  
iii. Date of first investigation: 07/05/2014  
iv. Date of follow-up investigation: .....  
v. Time investigation started: 09:00 HRS  
vi. Estimated quantity spilled: NIL

4. Site Details

- i. Site/Location: 10" C/CREEK / TERIDABA PIPELINE AT AZAGBENE  
ii. Position of Spill/Leak: N 04° 47' 33.2" E 005° 45' 00.1"

iii. Spill area

- ☐ Land      ☒ Swamp      ☐ Freshwater      ☐ Mangrove      ☐ Coastline  
☐ Near shore      ☐ Offshore      ☐ Others (Specify) .....

iv. Structural Controls in Place

- ☐ Boom      ☐ Trenches      ☐ Bund Wall      ☐ Sorbents      ☐ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock      ☐ 10 0'Clock      ☐ 2 0'Clock      ☐ 3 0'Clock  
☐ 4 0'Clock      ☐ 5 0'Clock      ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil      ☐ Condensate      ☐ Chemicals      ☐ Refined Products  
☐ Others (Specify) .....

iii. Facility

- ☒ Pipeline      ☐ Flow Line      ☐ Wellhead      ☐ Manifold      ☐ Flow Station      ☐ Rig  
☐ Storage Tank      ☐ Compressor Plant  
☐ Others (Specify) .....

iv. Cause of Spill

- ☐ Corrosion      ☐ Equipment Failure      ☒ Third Party Interference      ☐ Accident  
☐ Operational Error      ☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks      ☐ Drilled Holes      ☐ Blasting      ☒ Theft      ☐ Acid  
☐ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland   ☐ Fish Pond   ☐ Vegetation   ☐ Fishing Net   ☐ Surface water  
☐ Venerable Objects   ☐ Others (Specify) .....

### ii. Nature of impact

- ☐ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
☐ Dead floating crabs   ☐ Withering of vegetation   ☐ Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW   ☐ Outside Company's facility/ROW

## 7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m<sup>2</sup>)

- i. .... i. ....  
 ii. .... ii. ....  
 iii. .... iii. ....  
 iv. .... iv. ....

(c) Creek/Creek lets   ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(d) Swamp   ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(e) River   ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(f) Shoreline/water   ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☐ Foot    ☒ Boat    ☐ Aircraft

11. Remarks/Recommendation. UNKNOWN PERSON(S) INSTALLED 3" NIPPLES AT 12 O'CLOCK  
POSITION FOR CRUDE OIL THEFT ACTIVITIES / NO FURTHER CLEAN-UP  
IS REQUIRED.

12. Time Investigation ended..... 2:00 PM