



2014/LAR/129/491

## NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

### JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field.

1. Company: NAD C

#### 2. Type of Complaint/Incident:

☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution

☒ Others (Specify) GASEOUS EMISSION

#### 3. Incident Details

i. Date of Incident: 5TH JUNE 2014 ii. Date first reported: 5TH JUNE 2014

iii. Date of first investigation: 6TH JUNE 2014

iv. Date of follow-up investigation: .....

v. Time investigation started: 1430 HRS

vi. Estimated quantity spilled: NIL

#### 4. Site Details

i. Site/Location: EBOCHA 3 L FLOWLINE ALONG OLD EBOCHA FERRY ROAD BY NDONIRI ONELEA RIVERS STATE

ii. Position of Spill/Leak: 05°27'09.4"N → LEAK PT 1  
006°41'11.0"E → LEAK PT 2  
05°27'08.2"N → LEAK PT 1  
006°41'08.6"E

#### iii. Spill area

☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify) .....

#### iv. Structural Controls in Place

☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify) .....

#### 5. Circumstances Around Spill Point

##### i. Visual observation of Hole Position

☒ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock

☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock 1 0'Clock

##### ii. Type of Oil Contaminant

☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (Specify) GASEOUS EMISSION

##### iii. Facility

☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify) .....

##### iv. Cause of Spill

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (Specify) .....

##### v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☒ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water  
☐ Venerable Objects ☐ Others (Specify) ..... NIL

### ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes  
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) ..... NIL

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

## 7. Extent of Impact

(a) Community (Indicate name)

- i. .... NIL .....  
ii. ....  
iii. ....  
iv. ....

(b) Land (Indicate area in m<sup>2</sup>)

- i. .... NIL .....  
ii. ....  
iii. ....  
iv. ....

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken..... NIL

10. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

11. Remarks/Recommendation.....

NAOC should make available staff  
by security personnel at facility sites in ensuring  
good security surveillance.

12. Time Investigation ended.....

1500 HRS