



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NIGERIAN AGIP OIL COMPANY LIMITED

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 02/07/14 ii. Date first reported: 03/07/14
iii. Date of first investigation: 04/07/14
iv. Date of follow-up investigation:
v. Time investigation started: 2:15 PM
vi. Estimated quantity spilled: 32.9 BBLS

4. Site Details

- i. Site/Location: OSHIE 7 TBG FLOWLINE AKARAOW
ii. Position of Spill/Leak: (A) N 05° 05' 39.1" (B) N 05° 05' 35.9"
E 006° 30' 38.2" E 006° 30' 39.2"
iii. Spill area
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☒ Others (Specify) SEASONAL SWAMP
iv. Structural Controls in Place
☒ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock
☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i Properties impacted by the incident

☐Farmland ☐Fish Pond ☒Vegetation ☐Fishing Net ☐Surface water
☐Venerable Objects ☐Others (specify).....

ii. Nature of impact

☒Oil stained vegetation ☐Oil stained fishing nets ☐Dead floating fishes
☐Dead floating crabs ☐Withering of vegetation ☐Others.....

iii. Delineation of impacted area

☒Within Company's facility/ROW ☒Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

i.
ii.
iii.
iv.

b) Land*(indicate area in m²)

i.
ii.
iii.....
iv.

b) Creeks/Creek lets

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐Tidal

☐Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken..... *NIL*

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation.....

*Repair should be carried out
as soon as possible and increase in
surveillance.*

12. Time investigation ended.....

4:05 HRS