

NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NDOC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify):

3. Incident Details

- i. Date of Incident: 31/07/14 ii. Date first reported: 31/07/14
iii. Date of first investigation: 2/08/14
iv. Date of follow-up investigation: 4/08/14
v. Time investigation started: 17:05 HRS
vi. Estimated quantity spilled: 7.978 Bbls

4. Site Details

- i. Site/Location: TAYLOR CREEK 2SS Flow Line close TO TAYLOR
ii. Position of Spill/Leak: HOS 10 09.2 EUG 26' 37.6'

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify):

iv. Structural Controls in Place

- ☒ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify):

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock ☒ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify):

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify):

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify):

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify):

6. Impact of Incident

i Properties impacted by the incident

☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead-floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

☐ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²)

i. 1,141.99 m²
 ii.
 iii.
 iv.

b) Creeks/Creek lets

☐ Tidal ☒ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☐ Aircraft

11. Remarks/Recommendation..... *NABOC should increase of Surveillances*
to reduces issues of oil theft.