



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: ADDAX

2. Type of Complaint/Incident:

☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify) GAS LEAK

3. Incident Details

i. Date of Incident: 14-11-2014 ii. Date first reported: 14-11-2014

iii. Date of first investigation: 15-11-2014

iv. Date of follow-up investigation:

v. Time investigation started: 1:00 PM

vi. Estimated quantity spilled: NIL

4. Site Details

i. Site/Location: IZOMBE UGBELE, IMO STATE

ii. Position of Spill/Leak: N05° 36' 92.7"

iii. Spill area

☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) NON

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☒ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☐ 3 O'Clock

☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (Specify) GAS LEAK

iii. Facility

☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify)

iv. Cause of Spill

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland
- ☐ Fish Pond
- ☐ Vegetation
- ☐ Fishing Net
- ☐ Surface water
- ☐ Venerable Objects
- ☐ Others (Specify) NOT APPLICABLE

ii. Nature of impact

- ☐ Oil stained vegetation
- ☐ Oil stained fishing nets
- ☐ Dead floating fishes
- ☐ Dead floating crabs
- ☐ Withering of vegetation
- ☐ Others (Specify) NIL

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
- ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
- ii.
- iii.
- iv.

(b) Land (Indicate area in m²)

- i.
- ii.
- iii.
- iv.

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... **NOT APPLICABLE**

10. Investigation carried out by

☒ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation..... **A leak point was observed as a result of heck saw cut within the facility.**
..... **Addex should intensify surveillance.**

12. Time Investigation ended..... **1:35 PM**

13. Name and Signature of Participants