



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: Nigeria Agip Oil Company

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 25-11-2014 ii. Date first reported: 29-11-2014
iii. Date of first investigation: 25-11-2014
iv. Date of follow-up investigation: 29-11-2014
v. Time investigation started: 15:45 HRS
vi. Estimated quantity spilled: 6.47 bbls

4. Site Details

- i. Site/Location: IDU 8SS NEAR MAMFOLD, IDU COMMUNITY, ONE LGA, RIVERS STATE.
ii. Position of Spill/Leak: N 05° 15' 34.0" E 006° 34' 23.5"

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock ☒ 10 0'Clock ☒ 2 0'Clock ☒ 3 0'Clock
☒ 4 0'Clock ☒ 5 0'Clock ☒ 6 0'Clock 9 → 12 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☐ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland ☒ Fish Pond ☒ Vegetation ☒ Fishing Net ☒ Surface water
☒ Venerable Objects ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation ☒ Oil stained fishing nets ☒ Dead floating fishes
☒ Dead floating crabs ☒ Withering of vegetation ☒ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
ii.
iii.
iv.

(b) Land (Indicate area in m²)

- i.
ii.
iii.
iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☒ Mapping

9. Samples taken..... NIL

10. Investigation carried out by

☒ Foot ☐ Boat ☒ Aircraft

11. Remarks/Recommendation..... Effect clean-up of impacted site, improve surveillance around facilities

12. Time Investigation ended..... 2:30 PM

13. Name and Signature of Participants

❖ NOSDRA

1. Alagosa Ernest B Alagosa 28/11/14

2.

3.

❖ DPR

1. Pius Edun 28/11/14

2.

3.

❖ STATE MINISTRY OF ENVIRONMENT

1. Ejoku George 28/11/14

2.

3.

❖ LOCAL GOVERNMENT COUNCIL

1.

2.

3.

❖ COMPANY

1. Tobin Obinna C. Ombiri 28/11/14

2.

3.

❖ COMMUNITY

1. Okoni Josiah 28/11/14

2.

3.