



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: NADC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☒ Fire/Explosion ☒ Drilling Mud/Chemical Pollution
☒ Others (Specify)

3. Incident Details

- i. Date of Incident: 10-01-2015 ii. Date first reported:
iii. Date of first investigation: 10-01-2015
iv. Date of follow-up investigation:
v. Time investigation started: 13.04 HRS
vi. Estimated quantity spilled: TWELVE (12) BARRELS

4. Site Details

- i. Site/Location: 18" TEBIDABA BRASS PIPELINE AT OYEREGBENE(1)
ii. Position of Spill/Leak: NO 4° 30' 25.0" E 006° 02' 57.6"

iii. Spill area

- ☒ Land ☒ Swamp ☒ Freshwater ☒ Mangrove ☒ Coastline
☒ Near shore ☒ Offshore ☒ Others (Specify)

iv. Structural Controls in Place

- ☒ Boom ☒ Trenches ☒ Bund Wall ☒ Sorbents ☒ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0' Clock ☒ 10 0' Clock ☒ 2 0' Clock ☒ 3 0' Clock
☒ 4 0' Clock ☒ 5 0' Clock ☒ 6 0' Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☒ Condensate ☒ Chemicals ☒ Refined Products
☒ Others (Specify)

iii. Facility

- ☒ Pipeline ☒ Flow Line ☒ Wellhead ☒ Manifold ☒ Flow Station ☒ Rig
☒ Storage Tank ☒ Compressor Plant
☒ Others (Specify)

iv. Cause of Spill

- ☒ Corrosion ☒ Equipment Failure ☒ Third Party Interference ☒ Accident
☒ Operational Error ☒ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☒ Drilled Holes ☒ Blasting ☒ Theft ☒ Acid
☒ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☒ Farmland
 ☒ Fish Pond
 ☒ Vegetation
 ☒ Fishing Net
 ☒ Surface water
☒ Venerable Objects
 ☒ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation
 ☒ Oil stained fishing nets
 ☒ Dead floating fishes
☒ Dead floating crabs
 ☒ Withering of vegetation
 ☒ Others (Specify)

iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW
 ☒ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m²)

- i. *NA* i.
 ii. *NA* ii.
 iii. *NA* iii.
 iv. iv.

(c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>

(d) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>

(e) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>

(f) Shoreline/water

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>
<i>NA</i>	<i>NA</i>	<i>NA</i>	<i>NA</i>

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☒ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation.....

Adequate Surveillance should be improved
on the company's facilities.

12. Time Investigation ended.....