



## NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

### JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC (FID 1243855)

#### 2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

#### 3. Incident Details

- i. Date of Incident: 02/09/2014 ii. Date first reported: 05/09/2014  
iii. Date of first investigation: 08/09/2014  
iv. Date of follow-up investigation: .....  
v. Time investigation started: 12:30 pm  
vi. Estimated quantity spilled: 4 Barrels

#### 4. Site Details

- i. Site/Location: UBLE w/4s Flow Line  
ii. Position of Spill/Leak: (Minna (mid belt) N 12321.36, E 454981.22  
(5°6'14.9"N, 006°33'18.3"E)  
iii. Spill area  
☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline  
☐ Near shore ☐ Offshore ☐ Others (Specify) .....

#### iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) .....

#### 5. Circumstances Around Spill Point

##### i. Visual observation of Hole Position

- ☐ 12 0'Clock ☒ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock  
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

##### ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products  
☐ Others (Specify) .....

##### iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig  
☐ Storage Tank ☐ Compressor Plant  
☐ Others (Specify) .....

##### iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident  
☐ Operational Error ☐ Others (Specify) .....

##### v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid  
☐ Others (Specify) .....

**6. Impact of Incident**

**i Properties impacted by the incident**

- ☒ Farmland   ☐ Fish Pond   ☐ Vegetation   ☐ Fishing Net   ☐ Surface water  
☐ Venerable Objects   ☐ Others (specify).....

**ii. Nature of impact**

- ☒ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
☐ Dead floating crabs   ☐ Withering of vegetation   ☐ Others.....

**iii. Delineation of impacted area**

- ☒ Within Company's facility/ROW   ☐ Outside Company's facility/ROW

**7. Extent of Impact**

**a) Community (indicate name)**

- i. ....  
ii. ....  
iii. ....  
iv. ....

**b) Land (indicate area in m<sup>2</sup>)**

- i. ....  
ii. ....  
iii. ....  
iv. ....

**b) Creeks/Creek lets**

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

**c) Swamp**

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

**d) River**

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

**e) Shoreline/water**

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. **Photograph/Map/Chart Ref.**

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. **Samples taken**.....

10. **Investigation carried out by**

☒ Foot    ☐ Boat    ☐ Aircraft

11. **Remarks/Recommendation**.....

SPDC should improve on their  
surveillance team. Clean up should be done.

12. **Time investigation ended**.....