



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: Nigeria Agip Oil Company

2. Type of Complaint/Incident:

☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☒ Others (Specify) Condensate

3. Incident Details

i. Date of Incident: 13/03/15 ii. Date first reported: 13/03/15

iii. Date of first investigation: 14/03/15

iv. Date of follow-up investigation: .....

v. Time investigation started: 17:04 HRS

vi. Estimated quantity spilled: 5 barrels

4. Site Details

i. Site/Location: Azuoma Well 6 at Olujobobiri

ii. Position of Spill/Leak: 3 O'Clock

iii. Spill area

☐ Land ☐ Swamp ☒ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify) .....

iv. Structural Controls in Place

☒ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

☐ 12 O'Clock ☐ 10 O'Clock ☐ 2 O'Clock ☒ 3 O'Clock

☐ 4 O'Clock ☐ 5 O'Clock ☐ 6 O'Clock

ii. Type of Oil Contaminant

☐ Crude Oil ☒ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (Specify) .....

iii. Facility

☐ Pipeline ☐ Flow Line ☒ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify) .....

iv. Cause of Spill

☐ Corrosion ☒ Equipment Failure ☐ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland   ☐ Fish Pond   ☒ Vegetation   ☐ Fishing Net   ☒ Surface water  
☐ Venerable Objects   ☐ Others (Specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
☐ Dead floating crabs   ☒ Withering of vegetation   ☐ Others (Specify) .....

### iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW   ☒ Outside Company's facility/ROW

## 7. Extent of Impact

### (a) Community (Indicate name)

- i. ....  
ii. ....  
iii. ....  
iv. ....

### (b) Land (Indicate area in m<sup>2</sup>)

- i. ....  
ii. ....  
iii. ....  
iv. ....

### (c) Creek/Creek lets

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (d) Swamp

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (e) River

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

### (f) Shoreline/water

☐ Tidal

☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☐ Foot    ☒ Boat    ☐ Aircraft

11. Remarks/Recommendation..... *Immediate fix of Choke valve &*  
*Delimitation Survey were repairs are*  
*completed*

12. Time Investigation ended..... *17:45 HRS*