NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY

JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. **Company:** NAOC

2. **Type of Complaint/Incident:**

☑ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution

☐ Others (Specify) .....

3. **Incident Details**

i. Date of Incident: 09/06/15 ii. Date first reported: 09/06/15

iii. Date of first investigation: 09/06/15

iv. Date of follow-up investigation:.....

v. Time investigation started: 10:58 am

vi. Estimated quantity spilled: 7Barrels

4. **Site Details**

i. Site/Location: 18" TEBIDABA/BRASS PIPELINE AT OYEREGBENE BAYELSA

ii. Position of Spill/Leak: N04 29 38 2, E006 04 51 6

iii. **Spill area**

☐ Land ☑ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify).....

iv. **Structural Controls in Place**

☑ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify).....

5. **Circumstances Around Spill Point**

i. **Visual observation of Hole Position**

☑ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock

☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. **Type of Oil Contaminant**

☑ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products

☐ Others (Specify) .....

iii. **Facility**

☑ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig

☐ Storage Tank ☐ Compressor Plant

☐ Others (Specify) .....

iv. **Cause of Spill**

☐ Corrosion ☐ Equipment Failure ☑ Third Party Interference ☐ Accident

☐ Operational Error ☐ Others (Specify) .....

v. **Visible Sign of Third Party Interference**

☑ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid

☐ Others (Specify) .....

6. **Impact of Incident**

i. **Properties Impacted by the incident**

☐ Farmland ☐ Fish Pond ☑ Vegetation ☐ Fishing Net ☑ Surface water

☐ Venerable Objects ☐ Others (Specify) .....

ii. **Nature of impact**

☑ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes

☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify) .....

iii. **Delineation of Impacted area**

☐ Within Company's facility/ROW ☑ Outside Company's facility/ROW

7. **Extent of Impact**

(a) **Community** (*Indicate name*)

i. OYEREGBENE

ii. .....

iii. .....

iv. .....

(b) **Land** (*Indicate area in m^2*)

i. 883 m^2.

ii. .....

iii. .....

iv. .....

(c) **Creek/Creek lets** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) **Swamp** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) **River** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) **Shoreline/water** ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☑ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... NIL .....

10. Investigation carried out by

☐ Foot ☑ Boat ☐ Aircraft

11. Remarks/Recommendation..THE 18" PIPELINE WAS CUT BY UNKNOWN PERSON AT 12"OCLOCK POSITION. NO RECOVERY WAS DONE AS AT THE TIME OF J I V CLEAN UP SHOULD BE CARRIED OUT IN THE AREA

12. Time Investigation ended..... 1:50 pm .....

13. Name and Signature of Participants

- NOSDRA
  1. Enaholo Raphael - Ugbenose 9/6/15
  2. .....
  3. .....
- DPR
  1. .....
  2. .....
  3. .....
- STATE MINISTRY OF ENVIRONMENT
  1. OBANOE AKPOTU 09/06/2015
  2. .....
  3. .....
- LOCAL GOVERNMENT COUNCIL
  1. .....
  2. .....
  3. .....
- COMPANY
  1. Okhom Davies NAOC CRV 09/06/15
  2. ELEdit O.J Nnethe 09/06/2015.
  3. .....
- COMMUNITY
  1. .....
  2. .....
  3. .....