



JOINT INVESTIGATION VISIT (JIV) FORM

1. Company: NAOC

☐ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify) ... GASEOUS EMISSION ...

i. Date of Incident: 03:06:2015 ii. Date first reported: 03:06:2015
iii. Date of first investigation: 03:06:2015
iv. Date of follow-up investigation: _____
v. Time investigation started: 1345 Hrs
vi. Estimated quantity spilled: _____

Details

i. Site/Location: EBOLHA 4L XS FLOWLINE @ ORATH RIVER CROSSING, EBOLHA.

ii. Position of Spill/Leak: ① N 05° 26' 58.3" E 006° 41' 10.5"

iii. Spill area ① N 05° 26' 58.4" E 006° 40' 10.3"

☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline

☐ Near shore ☐ Offshore ☐ Others (Specify).....

☐ Boom ☐ Trench ☐ Bund Wall ☐ Sorbents ☐ Others (Specify).....

i. Visual observation of Hole 1 Migration

☐ 12 0° Clock ☒ 10 0° Clock ☐ 2 0° Clock ☐ 3 0° Clock
☐ 4 0° Clock ☐ 1 0° Clock ☐ 6 0° Clock ☒ 1 0° Clock

☐ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify) Gaseous Emission

☐ Pipeline ☒ Platform ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error Others (Specify)

☐ Hacksaw Marks ☒ Tool Marks ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify) Two drilled holes of 6mm and 4mm @ 10' each each.
At a distance of 3-5m on the same
flow line.

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (Specify) *N/A*

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others (Specify)

iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

(a) Community (Indicate name)

- i.
ii.
iii.
iv.

(b) Land (Indicate area in m²)

- i.
ii.
iii.
iv.

(c) Creek/Creek lets ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(d) Swamp ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(e) River ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

(f) Shoreline/water ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

8. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

9. Samples taken..... NO

10. Investigation carried out by

☐ Foot ☐ Boat ☐ Aircraft

11. Remarks/Recommendation.....

The PW was Carryout successfully.
Repairs was Carryout Immediately after Inspecter.
NAOC should Insensified ~~out~~ its Surveillance on it