



1428935

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

i. Company: SPDC

**2. Type of Complaint/Incident:**

- ☒ Oil Pollution    ☐ Fire/Explosion    ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

**3. Incident Details**

- i. Date of Incident: 27-06-2015    ii. Date first reported: 29-06-2015  
iii. Date of first investigation: 30-06-2015  
iv. Date of follow-up investigation: .....  
v. Time investigation started: 11:40 Hours  
vi. Estimated quantity spilled: .....

**4. Site Details**

- i. Site/Location: OBIGBO WELL 10T GASLIFT WELL HEAD AT UMUDINOR  
ii. Position of Spill/Leak: N04°52'50.6" E007°7'24.8"  
iii. Spill area

- ☒ Land    ☐ Swamp    ☐ Freshwater    ☐ Mangrove    ☐ Coastline  
☐ Near shore    ☐ Offshore    ☐ Others (Specify) .....

**iv. Structural Controls in Place**

- ☐ Boom    ☐ Trenches    ☐ Bund Wall    ☐ Sorbents    ☐ Others (Specify) NATURAL DEPRESSION

**5. Circumstances Around Spill Point**

**i. Visual observation of Hole Position**

- ☐ 12 O'Clock    ☐ 10 O'Clock    ☐ 2 O'Clock    ☐ 3 O'Clock  
☐ 4 O'Clock    ☐ 5 O'Clock    ☐ 6 O'Clock

**ii. Type of Oil Contaminant**

- ☒ Crude Oil    ☐ Condensate    ☐ Chemicals    ☐ Refined Products  
☐ Others (Specify) .....

**iii. Facility**

- ☐ Pipeline    ☐ Flow Line    ☒ Wellhead    ☐ Manifold    ☐ Flow Station    ☐ Rig  
☐ Storage Tank    ☐ Compressor Plant  
☐ Others (Specify) .....

**iv. Cause of Spill**

- ☐ Corrosion    ☐ Equipment Failure    ☒ Third Party Interference    ☐ Accident  
☐ Operational Error    ☐ Others (Specify) .....

**v. Visible Sign of Third Party Interference**

- ☐ Hacksaw Marks    ☐ Drilled Holes    ☐ Blasting    ☒ Theft    ☐ Acid  
☐ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland   ☐ Fish Pond   ☐ Vegetation   ☐ Fishing Net   ☐ Surface water  
☐ Venerable Objects   ☐ Others (Specify) .... N/A

### ii. Nature of impact

- ☐ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
☐ Dead floating crabs   ☐ Withering of vegetation   ☐ Others (Specify) .... N/A

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW   ☐ Outside Company's facility/ROW

## 7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m<sup>2</sup>)

i. .... i. ....

ii. .... ii. ....

iii. .... iii. ....

iv. .... iv. ....

(c) Creek/Creek lets   ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(d) Swamp   ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(e) River   ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(f) Shoreline/water   ☐ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot    ☐ Boat    ☐ Aircraft

11. Remarks/Recommendation..... JIV successful and concluded.....

SPDC should strengthen the security network  
on their facility.

12. Time Investigation ended.....