



**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

*Note: This JIV form is to be completed and signed by all participating parties in the field*

1. Company: ..... N.A.O.C .....

2. Type of Complaint/Incident:

- ☒ Oil Pollution      ☐ Fire/Explosion      ☐ Drilling Mud/Chemical Pollution  
☐ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 02/02/15 ..... ii. Date first reported: 02/02/15 .....  
iii. Date of first investigation: 02/02/15 .....  
iv. Date of follow-up investigation: N/A .....  
v. Time investigation started: 10:03 hrs .....  
vi. Estimated quantity spilled: 3566ls .....

4. Site Details

- i. Site/Location: 18" TERIDABA/BRASS PIPELINE AT BABERAGBENG .....  
ii. Position of Spill/Leak: N 04° 30' 43.1" E 006° 01' 58.0" .....  
iii. Spill area  
☐ Land      ☒ Swamp      ☐ Freshwater      ☐ Mangrove      ☐ Coastline  
☐ Near shore      ☐ Offshore      ☐ Others (Specify) .....  
iv. Structural Controls in Place N/A  
☐ Boom      ☐ Trenches      ☐ Bund Wall      ☐ Sorbents      ☐ Others (Specify) .....

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 O'Clock      ☐ 10 O'Clock      ☐ 2 O'Clock      ☐ 3 O'Clock  
☐ 4 O'Clock      ☐ 5 O'Clock      ☐ 6 O'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil      ☐ Condensate      ☐ Chemicals      ☐ Refined Products  
☐ Others (Specify) .....

iii. Facility

- ☒ Pipeline      ☐ Flow Line      ☐ Wellhead      ☐ Manifold      ☐ Flow Station      ☐ Rig  
☐ Storage Tank      ☐ Compressor Plant  
☐ Others (Specify) .....

iv. Cause of Spill

- ☐ Corrosion      ☐ Equipment Failure      ☒ Third Party Interference      ☐ Accident  
☐ Operational Error      ☐ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks      ☐ Drilled Holes      ☐ Blasting      ☒ Theft      ☐ Acid  
☐ Others (Specify) .....



## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☐ Farmland   ☐ Fish Pond   ☒ Vegetation   ☐ Fishing Net   ☐ Surface water  
☐ Venerable Objects   ☐ Others (Specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation   ☐ Oil stained fishing nets   ☐ Dead floating fishes  
☐ Dead floating crabs   ☐ Withering of vegetation   ☐ Others (Specify) .....

### iii. Delineation of Impacted area

- ☐ Within Company's facility/ROW   ☒ Outside Company's facility/ROW

## 7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m<sup>2</sup>)

- i. BABERAGRENE ..... i. ....  
 ii. .... ii. ....  
 iii. .... iii. ....  
 iv. .... iv. ....

(c) Creek/Creek lets   ☒ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(d) Swamp   ☒ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(e) River   ☒ Tidal   ☐ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(f) Shoreline/water   ☐ Tidal   ☐ Non-tidal

| NAME     | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|----------|--------------------|-----------------|----------------|
| <u> </u> | <u> </u>           | <u> </u>        | <u> </u>       |
|          |                    |                 |                |
|          |                    |                 |                |
|          |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☐ Video coverage    ☐ Mapping

9. Samples taken..... *N/A* .....

10. Investigation carried out by

☐ Foot    ☒ Boat    ☒ Aircraft

11. Remarks/Recommendation..... *N/A* *Should increase*  
*surveillance on its facilities.* .....