



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: N.A.O.C

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 04/02/2015 ii. Date first reported: 04/02/15
iii. Date of first investigation: 04/02/15
iv. Date of follow-up investigation: N/A
v. Time investigation started: 1043 hrs
vi. Estimated quantity spilled: 40 bbls.

4. Site Details

- i. Site/Location: 18" TEBUABA BRASS PIPELINE AT LAGOS GREENE
ii. Position of Spill/Leak: N 04° 28' 30.0" E 006° 07' 51.7"

iii. Spill area

- ☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☐ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☒ Pipeline ☐ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i. Properties Impacted by the incident

- ☐ Farmland
- ☐ Fish Pond
- ☒ Vegetation
- ☐ Fishing Net
- ☐ Surface water
- ☐ Venerable Objects
- ☐ Others (Specify)

ii. Nature of impact

- ☒ Oil stained vegetation
- ☐ Oil stained fishing nets
- ☐ Dead floating fishes
- ☐ Dead floating crabs
- ☐ Withering of vegetation
- ☐ Others (Specify)
- iii. Delineation of Impacted area
- ☐ Within Company's facility/ROW

☒ Outside Company's facility/ROW
7. Extent of Impact
- (a) Community (Indicate name)
- (b) Land (Indicate area in m²)
- i. LAGOS GREENE SILGALGA

i.

ii.

ii.

iii.

iii.

iv.

iv.
- (c) Creek/Creek lets
- ☒ Tidal

☐ Non-tidal
- | NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
| | | | |
| | | | |
| | | | |
| | | | |
- (d) Swamp
- ☒ Tidal

☐ Non-tidal
- | NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
| | | | |
| | | | |
| | | | |
| | | | |
- (e) River
- ☒ Tidal

☐ Non-tidal
- | NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
| | | | |
| | | | |
| | | | |
| | | | |
- (f) Shoreline/water
- ☐ Tidal

☐ Non-tidal
- | NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
| ll | ll | ll | ll |
| | | | |
| | | | |
| | | | |

8. Photograph/Map/Chart Ref.

☒ Still photographs ☒ Video coverage ☐ Mapping

9. Samples taken..... *N/A*

10. Investigation carried out by

☐ Foot ☒ Boat ☒ Aircraft

11. Remarks/Recommendation..... *21 AOC should increase*

surveillance on her facilities.