



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY JOINT INVESTIGATION VISIT (JIV) FORM

Note: This Form is to be completed and signed by all participating parties in the field in BLOCK letters

1. Company: NAOC
2. Type of Complaint/Incident:
☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify).....
3. Incident Details
i. Date of Incident: 11/10/15 ii. Date first reported: 11/10/15
iii. Date of first investigation: 11/10/15 iv. Spill Incidence No.: 2015/SAR/245
v. Date of follow-up investigation:
vi. Time investigation started: 16:11 HRS
vii. Estimated quantity spilled(bbls): 10 viii. Quantity Recovered: NIL
4. Site Details
i. Site/Location: 18" TEBIDABA/BRASS P/L @ BENIKRUKRU
ii. State: BAYELSA iii. L.G.A.: SOUTHERN ISAM
iv. Spill Co-ordinates: N(m) 04° 32' 13.1"
E(m) 005° 58' 47.9"
v. Spill area
☐ Land ☒ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (specify).....
vi. Structural Controls in Place
☐ Boom ☐ Trenches ☒ Bund wall ☐ Sorbents ☐ Others (specify).....
5. Circumstances Around Spill Point
i. Visual observation of Hole Position
☒ 12 O' Clock ☐ 10 O' Clock ☐ 2 O' Clock ☐ 3 O' Clock
☐ 4 O' Clock ☐ 5 O' Clock ☐ 6 O' Clock
ii. Type of Oil contaminant
☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (specify)
- iii. Facility
☒ Pipeline ☐ Flow line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant ☐ Others (specify)
- iv. Cause Of Spill.
☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (specify).....
- v. Visible Sign of Third Party Interference
☐ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☒ Theft ☐ Acid
☐ Others (specify).....

6. Impact of Incident

i. Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☒ Vegetation ☐ Fishing Net ☒ Surface water
☐ Venerable Objects ☐ Others (specify).....

ii. Nature of impact

- ☒ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others.....

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Type of properties/ structures, if any, found outside the right-of-way

- ☐ Crops ☐ Fish Farm/ Pond ☐ Fishing net ☐ Makeshift
☐ Permanent ☐ Others

8. Extent of Impact

a) Community (indicate name)

- i.
 ii.
 iii.
 iv.

b) Land (indicate area in m²) 1.1 Ha.

- i.
 ii.
 iii.
 iv.

b) Creeks/Creek lets

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

c) Swamp

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

d) River

- ☐ Tidal ☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK

9. Photograph/Map/Chart Ref.

☒ Still photographs ☐ Video coverage ☐ Mapping

10. Samples taken.....

11. Investigation carried out by

☐ Foot ☐ Boat ☐ Aircraft

12. Remarks/Recommendation.....

The Cause of Spill is as result of Sabotage Since there was a visual installation of 3" valve on the Pipeline at 12 O'clock position.

13. Time investigation ended 18:45 HRS