



2015\_1519547

**NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY**  
**JOINT INVESTIGATION VISIT (JIV) FORM**

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: ..... SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution      ☒ Fire/Explosion      ☒ Drilling Mud/Chemical Pollution  
☒ Others (Specify) .....

3. Incident Details

- i. Date of Incident: 4/11/2015      ii. Date first reported: 4/11/2015  
iii. Date of first investigation: 7/11/2015  
iv. Date of follow-up investigation: .....  
v. Time investigation started: 0900hrs  
vi. Estimated quantity spilled: 10 Bls

4. Site Details

- i. Site/Location: 16" EGBEMA ASSA P/L @ EKPEAGAH  
ii. Position of Spill/Leak: 005° 24' 57.0", E 006° 46' 51.9"

iii. Spill area

- ☒ Land      ☒ Swamp      ☒ Freshwater      ☒ Mangrove      ☒ Coastline  
☒ Near shore      ☒ Offshore      ☒ Others (Specify) .....

iv. Structural Controls in Place

- ☒ Boom      ☒ Trenches      ☒ Bund Wall      ☒ Sorbents      ☒ Others (Specify) ..... CONTAINMENT PIT.

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☒ 12 0'Clock      ☒ 10 0'Clock      ☒ 2 0'Clock      ☒ 3 0'Clock  
☒ 4 0'Clock      ☒ 5 0'Clock      ☒ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil      ☒ Condensate      ☒ Chemicals      ☒ Refined Products  
☒ Others (Specify) .....

iii. Facility

- ☒ Pipeline      ☒ Flow Line      ☒ Wellhead      ☒ Manifold      ☒ Flow Station      ☒ Rig  
☒ Storage Tank      ☒ Compressor Plant  
☒ Others (Specify) .....

iv. Cause of Spill

- ☒ Corrosion      ☒ Equipment Failure      ☒ Third Party Interference      ☒ Accident  
☒ Operational Error      ☒ Others (Specify) .....

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks      ☒ Drilled Holes      ☒ Blasting      ☒ Theft      ☒ Acid  
☒ Others (Specify) .....

## 6. Impact of Incident

### i. Properties Impacted by the incident

- ☒ Farmland  
 ☒ Fish Pond  
 ☒ Vegetation  
 ☒ Fishing Net  
 ☒ Surface water  
☒ Venerable Objects  
 ☒ Others (Specify) .....

### ii. Nature of impact

- ☒ Oil stained vegetation  
 ☒ Oil stained fishing nets  
 ☒ Dead floating fishes  
☒ Dead floating crabs  
 ☒ Withering of vegetation  
 ☒ Others (Specify) .....

### iii. Delineation of Impacted area

- ☒ Within Company's facility/ROW  
 ☒ Outside Company's facility/ROW

## 7. Extent of Impact

(a) Community (Indicate name)

(b) Land (Indicate area in m<sup>2</sup>)

- i. .... i. 0.24 Ha.  
 ii. .... ii. ....  
 iii. .... iii. ....  
 iv. .... iv. ....

(c) Creek/Creek lets

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(d) Swamp

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(e) River

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

(f) Shoreline/water

☒ Tidal

☒ Non-tidal

| NAME | DIRECTION OF SLICK | LENGTH OF SLICK | WIDTH OF SLICK |
|------|--------------------|-----------------|----------------|
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |
|      |                    |                 |                |

8. Photograph/Map/Chart Ref.

☒ Still photographs    ☒ Video coverage    ☐ Mapping

9. Samples taken.....

10. Investigation carried out by

☒ Foot    ☒ Boat    ☒ Aircraft

11. Remarks/Recommendation.....

SAC should intensify her surveillance  
and clean up the impacted area.  
Repairs commenced at the end of the Iw.

12. Time Investigation ended.....

13. Name and Signature of Participants