



NATIONAL OIL SPILL DETECTION AND RESPONSE AGENCY
JOINT INVESTIGATION VISIT (JIV) FORM

Note: This JIV form is to be completed and signed by all participating parties in the field

1. Company: SPDC

2. Type of Complaint/Incident:

- ☒ Oil Pollution ☐ Fire/Explosion ☐ Drilling Mud/Chemical Pollution
☐ Others (Specify)

3. Incident Details

- i. Date of Incident: 27/07/2015 ii. Date first reported:
iii. Date of first investigation: 26/01/2016
iv. Date of follow-up investigation: 29/01/2016
v. Time investigation started: 1300 HRS
vi. Estimated quantity spilled: 0.4 BARREL

4. Site Details

- i. Site/Location: UBIE SS F/L AT IDU-EKPEYE RIVERS STATE
ii. Position of Spill/Leak: N 05° 6' 49.1", E 006° 33' 23.5"

iii. Spill area

- ☒ Land ☐ Swamp ☐ Freshwater ☐ Mangrove ☐ Coastline
☐ Near shore ☐ Offshore ☐ Others (Specify)

iv. Structural Controls in Place

- ☐ Boom ☐ Trenches ☐ Bund Wall ☐ Sorbents ☐ Others (Specify)

5. Circumstances Around Spill Point

i. Visual observation of Hole Position

- ☐ 12 0'Clock ☐ 10 0'Clock ☐ 2 0'Clock ☒ 3 0'Clock
☐ 4 0'Clock ☐ 5 0'Clock ☐ 6 0'Clock

ii. Type of Oil Contaminant

- ☒ Crude Oil ☐ Condensate ☐ Chemicals ☐ Refined Products
☐ Others (Specify)

iii. Facility

- ☐ Pipeline ☒ Flow Line ☐ Wellhead ☐ Manifold ☐ Flow Station ☐ Rig
☐ Storage Tank ☐ Compressor Plant
☐ Others (Specify)

iv. Cause of Spill

- ☐ Corrosion ☐ Equipment Failure ☒ Third Party Interference ☐ Accident
☐ Operational Error ☐ Others (Specify)

v. Visible Sign of Third Party Interference

- ☒ Hacksaw Marks ☐ Drilled Holes ☐ Blasting ☐ Theft ☐ Acid
☐ Others (Specify)

6. Impact of Incident

i Properties impacted by the incident

- ☐ Farmland ☐ Fish Pond ☐ Vegetation ☐ Fishing Net ☐ Surface water
☐ Venerable Objects ☐ Others (specify)..... NIL

ii. Nature of impact

- ☐ Oil stained vegetation ☐ Oil stained fishing nets ☐ Dead floating fishes
☐ Dead floating crabs ☐ Withering of vegetation ☐ Others..... NIL

iii. Delineation of impacted area

- ☒ Within Company's facility/ROW ☐ Outside Company's facility/ROW

7. Extent of Impact

a) Community (indicate name)

- i. //
 ii. //
 iii. //
 iv. //

b) Land (indicate area in m²)

- i. //
 ii. //
 iii. //
 iv. //

b) Creeks/Creek lets

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>

c) Swamp

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>

d) River

☐ Tidal

☐ Non-tidal

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>

e) Shoreline/water

NAME	DIRECTION OF SLICK	LENGTH OF SLICK	WIDTH OF SLICK
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>
<u>//</u>	<u>//</u>	<u>//</u>	<u>//</u>

8. **Photograph/Map/Chart Ref.**

☒ Still photographs ☐ Video coverage ☐ Mapping

9. **Samples taken**.....

10. **Investigation carried out by**

☒ Foot ☐ Boat ☐ Aircraft

11. **Remarks/Recommendation**..... SPDC SHOULD CARRY OUT
REPAIRS AND IMPROVE SURVEILLANCE
ON ITS FACILITY.....

12. **Time investigation ended**..... 1400HRS.....